

Rosewood Creek Area A SEZ Restoration –Photographs

Photo Point 1- Upstream of existing culvert at upstream tie-in



Photo Point 1- October 16, 2012



Photo Point 1- June 12, 2013

Photo Point 2 – staging area at Northwood Blvd to become wetland in Phase 3



Photo Point 3 – downstream end of new culvert at Northwood Blvd



Photo Point 3- October 16, 2012



Photo Point 3- June 4, 2013

Photo Point 4 – Looking upstream from mid-channel tie-in



Photo Point 4- October 16, 2012



Photo Point 4- June 4, 2013

Photo Point 5 – Tie-in mid-channel



Photo Point 5- October 16, 2012



Photo Point 5- June 12, 2013

Photo Point 6 – Floodplain looking downstream



Photo Point 6- October 16, 2012



Photo Point 6- June 4, 2013

Photo Point 7 – Wet Area near Third Creek HOA Path



Photo Point 7- October 16, 2012



Photo Point 7- June 4, 2013

Photo Point 8 – Invasive Weed Location



Photo Point 8- October 16, 2012



Photo Point 8- June 4, 2013

Photo Point 9 – downstream tie-in



Photo Point 9- October 16, 2012



Photo Point 9- June 4, 2013

Photo Point 10 – Steep slope above downstream end of new channel



Photo Point 10- October 16, 2012



Photo Point 10- June 4, 2013

Photo Point 11 – Floodplain and willows clumps looking downstream on new channel



Photo Point 11- October 16, 2012



Photo Point 11- June 4, 2013